



Safety Point

Registration Number
UDYAM-AS-15-0003636

A House of everything in FIRE FIGHTING & INDUSTRIAL SAFETY EQUIPMENT

A. T. Road, Kenduguri, Near Petrol Pump, Jorhat - 785 010
☎ 94350-91609 (M) / 91015-40033 (M)

Reg. S. S. I. Unit Govt. of Assam

TEST CERTIFICATE

No. 18

Date: 21/11/2025



Certified that following Fire Extinguishers were
Tested & or Refilled and Hydro Test Serviced by us at

To: Hemalata handique Memorial Institute
Jorhat

Sl. No	Type of Fire Extinguisher	Qty. Refilled	Qty. Rejected
1.	Dry Chemical Powder Type Capacity Fire Extinguisher		
2.	Dry Chemical Powder Type Capacity Fire Extinguisher		
3.	ABC Stored Pressure Type <u>4 kg</u> Capacity Fire Extinguisher	<u>9 Nos</u>	<u>NIL</u>
4.	ABC Stored Pressure Type Capacity Fire Extinguisher		
5.	ABC Stored Pressure Type Capacity Fire Extinguisher		
6.	Co ₂ Type Capacity Fire Extinguisher		
7.	M/ Foam Type Capacity Fire Extinguisher		
TOTAL		<u>9 Nos</u>	

Last Tasting / Demonstration Program

DCP - Type	1. Co ₂ Cartridge	ABC Type	<u>✓</u> ABC Powder <u>ok</u>	CHECKED THREE MONTHS SAFETY POINT KENDUGURI JORHAT 9435091609
	2. DCP Powder		<u>✓</u> Pressure - <u>ok</u>	
	3. DCP Hose		<u>✓</u> Hope Pipe <u>ok</u>	
	4. Paint		Mfd. Date	

ABC & DCP-9KG/10KG SHOULD NOT BE OLDER THAN 10 YEARS

Hydrotest of 30kg / um² of 2.5 mins of CHECKING FIVE YEARS Checking Date
Ultrasonic thickness testing for
DCP -9kg / 10kg 1kg/2kg

Co² 2kg / 1kg Hydrotest CHECKING THREE MONTHS Checking Date
Refilling Co² Hose Pipe Paint. Co₂ 2kg/1kg. Mfd. Date

CO₂ 2KG / 1KG SHOULD NOT BE OLDER THAN 15 YEARS

Hydrotest of 30 kg/um² of 2.5 mins of CHECKING FIVE YEARS Checking Date
Ultrasonic thickness testing for Co²-2kg/1kg.

Reason of Rejection :

FIRE CAN START ANY TIME

Date of Refilling

21/11/2025

Next Due Date

20/11/2026



T
E
S
T
R
E
F
I
L
L
C
E
R
T
I
F
I
C
A
T
E



GOVT. OF ASSAM,
JORHAT FIRE & EMERGENCY SERVICES STATION,
JORHAT, ASSAM.

No. JH/1&ESS/NOC/62/ 213 /2022

Dt. 12.05.2022

To,
The Principal,
Hemlata Handiqui Memorial Institute,
Lichubari,
Jorhat.

SUB:- Fire Safety Certificate.

Ref:- Your letter No. HHMI/JFES-01/L-14/22-23 dated 12.05.2022.

Sir,

With reference to the above, I have the honour to inform you that official of Jorhat F&ES Station had visited and inspected the existing fire safety measures and found all portable fire extinguishers in good working condition.

However it is to be mentionable that formal NOC is issued from the O/o The Director, Fire & Emergency Services, Assam, Panbazar, Guwahati which is now under process.

Yours faithfully,

[Handwritten Signature]
12/05/2022

Senior Station Officer, Station Officer
Jorhat Fire & Emergency Services Station,
Jorhat, Assam.

GOVT. OF ASSAM

JORHAT FIRE & EMERGENCY SERVICES STATION, JORHAT, ASSAM

NO. JHT / F&ESS / 62 (B) / 574 / 23

Dated. 27.06.2023

To,

Ms. Arumima Bhuyan,
Hemalata Handique Memorial Institute,
Village No. 1, Chowdang Gaon, Dist. - Jorhat

Sub : CONDITIONS TO BE FULFILLED FOR IMPLEMENTATION OF FIRE PREVENTION AND FIRE SAFETY MEASURES IN THE EXISTING ASSAM TYPE EDUCATIONAL BUILDING COVERING FIVE BLOCKS OF 'HEMALATA HANDIQUE MEMORIAL INSTITUTE' ON THE PLOT OF LAND BEARING DAG NO. 16, 17, 18, 31, 32, 33, 89, PATTA NO. 236, 271, MOUZA - CHARAIBAHU, LOCATED AT VILLAGE NO. 1, CHOWDANG GAON, DIST. - JORHAT

Ref. Your Application No. FNESBNOC1/2023/01020 Dated 26.06.2023

Madam,

With reference to the subject cited above, you are asked to implement the following minimum Fire Prevention and Fire Safety measures in the existing Assam Type Educational building mentioned above at the above noted location for safety of lives and properties as well as the building itself.

After proper implementation of the following Fire Safety measures, Fire Safety "No Objection Certificate" may be considered.

MINIMUM REQUIREMENT OF FIRE PROTECTION, FIRE PREVENTION AND MEANS OF ESCAPE FOR THE EXISTING ASSAM TYPE EDUCATIONAL BUILDING COVERING 5 BLOCKS OF "HEMALATA HANDIQUE MEMORIAL INSTITUTE" AS PER NATIONAL BUILDING CODE OF INDIA - 2016

Sl. No.	FIRE PROTECTION MEASURES	Sl. No.	FIRE PREVENTION MEASURES AND MEANS OF ESCAPE
1	Fire Extinguishers :- a) Adequate nos. of ABC/CO ₂ extinguisher of 4 kg/4.5 kg capacity should be provided in each blocks. The extinguishers are so distributed that a person has to travel not more than 15 m to reach the nearest extinguisher or in each 100 sq. metre area. b) At least 2 (two) nos. of CO ₂ extinguisher of 4.5 kg capacity should be provided near the electric panel board main switch gear box. c) At least 3 (three) nos. of AFFF extinguisher of 9 L capacity should be installed near D.G. set. N.B.:- All fire extinguishers should be newly introduced Indian Standard - as per IS:15683/2006.	1	Electrical wiring should be of either conduit or concealed type.
2	Manually Operated Electric Fire Alarm system should be provided in the school building.	2	To eliminate fire hazards, good housekeeping both inside and outside of the building should be strictly maintained by the staff and management of the building.
3	A Fire point provision consisting of 3(three) nos. of water buckets, 3(three) nos. of sand buckets and 1(one) no. of ceiling hook should be provided in front of the school building.	3	Employee/staff/students must be trained to operate the fire safety installations.
		4	Emergency telephone numbers should be displayed in suitable place that easily seen by the staff and common people.

Above action should be completed by 26.07.2023 and upload compliance report from your end in time.

Yours faithfully

[Signature]
27/6/23

Sr. Station Officer

Jorhat Fire & Emergency Services

Sr. Station Officer
Jorhat Fire & Emergency -
Services Station,
Jorhat, Assam.

Form XI

FORM OF APPLICATION FOR COMPLIANCE REPORT OF FIRE SAFETY REPORT
SUGGESTIONS

To,

The Director,
Fire & Emergency Services, Assam
Panbazar, Guwahati - 1

Sir,

I/We Ms. Pitchi Gohain Gogoi on behalf of Ms. Gayatri Handiqui located at LICHUBARI PO CINNAMARA JORHAT holding District JORHAT do hereby inform you that Fire Prevention & Fire Safety measures have been provided in the Building/Premises as per recommendation by you vide your letter no. NIL dated 20/06/2025 and Para wise compliance report is enclosed.

You are requested kindly to take necessary action for grant of N.O.C for the above premises/building.

Contact Details :

1. Name in Full : Ms. Pitchi Gohain Gogoi
2. Telephone Number :
3. Mobile Number : 8761063412

P. Gohain Gogoi 5/8/25

Signature of the Applicant
Principal I/C

Hemalata Handiqui Memorial Institute
Jorhat, Assam
CBSE Aff : 230084

Received by :

1. Name & Designation :
2. Date & Time :





HEMALATA HANDIQUI MEMORIAL INSTITUTE

Institute, P.O. - Chinnamara, Jorhat - 781005, Assam

Contact Number: 876063412, Email ID: hlmi.jorhat@gmail.com

Website: www.hlmi.edu.in

HLMI/1-50/TS-2/25-26

Date: 21/08/2025

The Officer-in-Charge,
Fire Station,
Jorhat, Assam

Subject: Submission of Details of Responsible Persons for Fire Extinguisher Handling and Request for Fire Safety Certificate

Sir,

With due respect, this is to inform you that our institution is submitting the details of the persons designated as responsible for handling fire extinguishers in our premises. Along with their particulars, we are also enclosing their recent photographs for your records.

We kindly request you to acknowledge the same and keep the information on record for future reference. Further, we also request you to kindly issue the Fire Safety Certificate for our institution after due verification.

Thanking you,

Yours faithfully,

P. Gohain Gogoi
21/8/25
Pitichi Gohain Gogoi
Principal in Charge
Hemalata Handiqui Memorial Institute
Principal IC,
Hemalata Handiqui Memorial Institute



Enclosures:

1. List of designated persons with details
2. Photographs of Fire Extinguisher

List of Persons responsible for Fire Extinguisher handling:

Sl. No	Name of Person	Designation	Contact Number	Address	Photograph
1	Mr. Brojraj Boruah	Office Incharge	8638054076	Hemalata Handiqui Memorial Institute, Lichubari, Jorhat, Assam, Pin:785008	
2	Mr. Abidur Rahman	Security	8011288422	Hemalata Handiqui Memorial Institute, Lichubari, Jorhat, Assam, Pin:785008	
3	Mr. Prashant Kumar Thakur	Security	8721029764	Hemalata Handiqui Memorial Institute, Lichubari, Jorhat, Assam, Pin:785008	
4	Mr. Uttam Robi Das	Security	8133873924	Hemalata Handiqui Memorial Institute, Lichubari, Jorhat, Assam, Pin:785008	

Photos of Fire Extinguisher:

1. Fire Alarm, Main Building



2. Bike Stand , Office Building



3. Chemistry lab , Main Building



4. Computer Lab, Main Building



5. Near Electric Meter , Main Building



Photos of Fire Extinguisher:

6. Auditorium Hall



7. Auditorium Hall



8. Junior Section



9. Junior Section near Staff Room



10. Main Building near RO Filter



11. Office Building near Inverter



12. Generator

